


Titan Telescoping Flagpole “Interlocking Sleeve Replacement” Instructions

Tools needed:

Needle-Nose Plier & Phillips Screwdriver



Step 1:

To begin collapse pole and place on flat working surface (tabletop or workbench). Remove all accessories and hardware (ball top, flag & flag harnesses). **Figure 1**

Step 2:

Remove black cap and foam cushion from bottom of pole by taking out two screws. **Figure 2 & 3**




Figure 2




Figure 3



Figure 4

Step 3:

Slide tube sections out through bottom of pole to expose **BIS** (Bottom Interlocking Sleeve). With needle-nose pliers and screwdriver, remove screw and pin. Remove **BIS**. REPEAT to replace additional failed **BIS** parts as necessary. **Figure 4,5 & 6**




Figure 5



Figure 6

Step 4

To replace **TIS** (Top Interlocking Sleeve) depress both tabs and slide out failed part. Press in new **TIS**. **Figure 7, 8 & 9**



Figure 7



Figure 9

Step 5:

Reassemble flagpole by pushing sections up through the bottom. Make sure there are no loose pieces left in between pole sections.




Figure 8