



**BnD Flagpole Sales**

**Bud Butler**

1298 Bee Mountain Ridge Rd.  
Lenoir, NC 28645

Phone: 239-246-2874

Email: Budman650@att.net  
Web Site: www.bndflagpoles.com

# Titan Telescoping Flagpole "Interlocking Sleeve Replacement" Instructions

Tools needed:

Needle-Nose Plier & Phillips Screwdriver




## Step 1:


To begin collapse pole and place on flat working surface (tabletop or workbench). Remove all accessories and hardware (ball top, flag & flag harnesses). **Figure 1**

## Step 2:


Remove black cap and foam cushion from bottom of pole by taking out two screws. **Figure 2 & 3**



**Figure 2**




**Figure 3**



**Figure 4**

**Only the Phillips Head screw will turn!**



**Figure 5**




**Figure 6**

## Step 3:

Slide tube sections out through bottom of pole to expose **BIS** (Bottom Interlocking Sleeve). With needle-nose pliers and screwdriver, remove screw and pin. Remove **BIS**. REPEAT to replace additional failed **BIS** parts as necessary. **Figure 4,5 & 6**




**Figure 7**



**Figure 9**

## Step 4

To replace **TIS** (Top Interlocking Sleeve) depress both tabs and slide out failed part. Press in new **TIS**. **Figure 7, 8 & 9**



**Figure 8**

## Step 5:

Reassemble flagpole by pushing sections up through the bottom. Make sure there are no loose pieces left in between pole sections.